

NEW YORK STATE UNIFORM FIRE PREVENTION AND BUILDING CODE NOTICE OF VIOLATION



PAGE 1 OF PAGES OWNER/ighborhood House ADDREFFIEree Mile Harbor Road INSPECTION DATE12-92 East Hampton NY 11937 MJ-41 FAILURE TO CORRECT VIOLATIONS NOTED ON THIS REPORT OR ANY ATTACHMENTS WITHIN TIME LIMIT STATED MAY RESULT IN APPROPRIATE LEGAL ACTION AGAINST YOU OR YOUR ESTABLISHMENT AS DIRECTED BY LAW. **Annual Inspection** Annual Fire Prevention Permit has expired on 10-17-92, (application 1) enclosed). Please conspicuously post the enclosed maximum occupancy sign in the 2) meeting room. IT IS PUSTED IN WOM. Bilco type doors are in need of repair to prevent injury from someone 3) falling into basement. completion/19/92 Storage Shed #1 Liquid propane gas tank not permitted to be stored inside of a 4) building. - RE-WLATED "/12/62 Storage Shed #3 Junction box lacks protective cover plate. Electricity may be shut 5) off, but box still requires plate. Compute 1/19/92 Note: Fire violations require immediate compliance. You are required to take appropriate action to fix, repair, or otherwise remedy the conditions noted above. A re-inspection will be scheduled for the near future to confirm compliance.

If there are any questions regarding this matter, please feel free to contact this Office.

Enc.

cc: East Hampton Fire Department

November 24, 1992

Be advised you have the right to appeal the above determination or to apply for a variance. Such appeal or request for a variance must be made to the Department of State as prescribed by the Secretary of State.